



AL EBHAR Company for Oil Services LTD

Magnetic Particle Inspection Report (MPI)

CLIENT NAME:	Al Harith Company	DATE OF INSPECTION:	16/02/2026
LOCATION:	Al Harith Base	DATE OF NEXT INSPECTION:	15/08/2026
SPECIFICATION:	ASTM E-709 & BS EN 15635	JOB ORDER NO.:	Harith-MPI-26-001-MA/001
TYPE OF INSPECTION:	VISUAL & MPI Inspection	CERTIFICATE NO.:	Harith-MPI-26-001

Technical Data

Magnetization Unit:	AC YOKE	Serial No.:	4635	Calibration Date	10\2025
White Contrast Paint :	Magnaflux.	Batch No.:	008A009	Expired Date	07\2027
BLACK Ink :	Magnaflux.	Batch No.:	008A103	Expired Date	07\2027

Inspection Procedure

Serial number :	,LB001	Description :	LIFTING BEAM
Acceptance Criteria:	No Crack Allowed.	Test Procedure No.:	ASTM E-709
		Area Inspected :	Welding Area

INSPECTION RESULT

COMMENTS	PICTURE
*CLEANING	
*VISUALLY CHECK FOR ANY DAMAGE , WEAR	
*PERFORM MPI EXAMINATION	
*CHECK FOR CRACK DETECTION	

INSPECTION RESULT

VISUALLY : SURFACE INSPECTION OF WELDING AREAS (ACCEPTED)

MPI: FREE FROM SURFACE CRACKS OR ANY OTHER DISCONTINUITIES AT TIME OF INSPECTION ... (ACCEPTED)

FINAL RESULTS: THE ABOVE INSPECTED AREAS WERE ACCEPTED



Mag Current	System	Surface Preparation	PERSONNEL DETAILS
Permanent:	Wet:	Yes	Inspector Name : KARAR JABER
	Dry:	
Active:	Fluorescent:	Signature:
	Contrast B/W:	Yes	

